

The optical module remains powered on even after being removed



Overview

When the optical port of the optical module is frequently up or down, first confirm whether the optical module is abnormal, you can check the optical module alarm information to troubleshoot the optical module at both ends and connect the optical fiber; for the. When the optical port of the optical module is frequently up or down, first confirm whether the optical module is abnormal, you can check the optical module alarm information to troubleshoot the optical module at both ends and connect the optical fiber; for the. Have you ever experienced an unexpected network outage due to the failure of an SFP/SFP+ optical transceiver?

Network outages can bring your ability to communicate and work to a halt, and your IT team will likely be frantically looking for a solution. It is important to understand how to. If RX remains in alarm after reseal and cleaning → likely far-end TX is off/faulty or the path is open (physical break or discontinuity in the fiber link). Unplugged connector at one end or both ends. Patch panel mismatch (fiber not connected through the correct. The solution is to unplug the fiber and reinsert it into the SFP module interface until a “click” sound is heard, indicating the fiber connector and SFP module are properly connected. A non-Huawei certified optical module is used.



Article Content

Jan 08, 2026

Analyzing Abnormal Situations During Installation and Use of Optical ...

As core components of optical communication systems, the proper installation and use of optical modules directly impacts network stability. This article systematically identifies common ...

Dec 07, 2025

Troubleshooting Common SFP Module Issues

Learn how to troubleshoot common SFP module issues including physical faults, hardware damage, compatibility, and configuration errors. This guide provides step-by-step solutions to maintain ...

May 04, 2026

Troubleshooting Your Optical Transceiver: A ...

However, like any other electronic component, optical transceivers can encounter issues that may affect network performance. In this guide, we'll delve ...

Nov 23, 2025

Troubleshooting and Repairing Optical Transceiver Failures in ...

There was not much difference in the initial optical power of the OEM and third-party modules, but the third-party units lost power faster after continued runtime, and the signal was ...

Feb 17, 2026

Case Study: A Device Starts Only After the Optical Module Is Removed

The device must have Huawei certified optical modules installed. Non-Huawei certified optical modules cannot ensure transmission reliability and may affect service stability.

Jun 05, 2026

SFP doesn't work after link-down

There is RX power about -33dBm at one site and -19dBm at other site. After changing SFP's between this 2 side, RX power at the problematic site is -30dBm and it's enough to working ...

Jul 22, 2026

Optical module common faults and solutions

In this article, we will focus on teaching you how to troubleshoot and solve the common three categories of optical module failure. First, the transmission class of the optical module fault ...

Dec 30, 2025

Troubleshoot Fiber Links on Catalyst 9000 Series Switches

Even when the switch can notify about the violation of these thresholds, this is not always the case, making the problem harder to detect. To circumvent this, creating an Embedded Event ...

Jan 21, 2026

Fiber Optic Module Diagnostic & Troubleshooting Cheat-Sheet

If bias remains high after cleaning and reseating → the fiber optic module or the fiber run itself is nearing end-of-life and should be scheduled for replacement.

Nov 06, 2025

DS110DF111: the SFP optical port fails to be inserted and removed ...

For DS110DF111, it is followed by a 10G SFP optical module, but after repeated insertion and removal, the optical module cannot be used, and the link status is displayed down.

May 07, 2026

Troubleshooting Your Optical Transceiver: A Comprehensive Guide

However, like any other electronic component, optical transceivers can encounter issues that may affect network performance. In this guide, we'll delve into common optical transceiver ...

Contact Us

For more information, pricing, or custom solutions, please contact us:

Website: <https://www.chromadecksigns-eastrand.co.za>

Email: sales@chromadecksigns-eastrand.co.za

Phone: +32 2 318 5792

Address: Avenue Louise 500, 1050 Brussels, Belgium

This document is for informational purposes only. Specifications subject to change without notice.

